

075B

SITE	Elliott Shooting Park
ID#	med980768333
BREAK	2-2 Tetra Tech
OTHER	4-14-88

**TETRA TECH, INC**  
 A HONEYWELL SUBSIDIARY  
 847 WAYC NTER SUIT 08  
 4TH AND STATE AVENUE  
 KANSAS CITY KANSAS 64108  
 TELEPHONE (913) 522-9044

April 14, 1988

TO David Crawford, U S EPA Primary Contact  
 THRU <sup>RAN FOR</sup> Russell B Krohn, Tetra Tech, Inc Regional Manager  
 FROM <sup>DM</sup> D Mark Doolan, Tetra Tech, Inc Work Assignment Manager  
 SUBJECT Elliott Shooting Park Cleanup - Status Report - March 16, 1988  
 through April 13, 1988  
 Work Assignment #194

On April 13, 1988, TES IV representative Mark Doolan visited the site to assess the progress made since the last visit on March 15, 1988. Upon arrival, Mr Doolan met with Gene Mayfield of Kingston Construction to discuss the progress status and future plans for the cleanup progress. Mr Mayfield reported that only seven sections remain to be cleaned at this time, consisting of Sections P, Q, W, X, Y, Z, and EE (not all analytical results for the other sections have been submitted to U S EPA yet).

Currently, several large stockpiles are present on the site in the above mentioned sections that have failed EP Toxicity tests and cannot be hauled to the Lee's Summit Landfill without additional treatment. Mr Mayfield reports that an area in Section Q will be stripped within the next week and will be used as a stockpile area for the clay pigeon fragments that have been separated by the dry shaker sieve. Soil from the shaker sieve process is being stockpiled in Section X to be processed through the wet washing system.


While Mr Doolan was on site, Kingston Construction personnel were operating the shaker sieve in Section Z. The clay pigeon fragments were being stockpiled in Section P, and the fines were stockpiled at the wet washer in Section X. Mr Doolan obtained photographs (included) of the current site conditions. It was noted that the silt fence at the head of the drainage ditch in Section J has been destroyed and large amounts of sediments are washing into the ditch. Additionally, the fence around the retention pond in Section Z was completely down during this site visit. Landscaping around the ECA Building, with the exception of Section EE has been completed. The ECA property currently appears to be adequately protected from runoff from the Elliott property.

40165446



SUPERFUND RECORDS

ON SCENE PHOTOGRAPHS



Exp Number 1

Date 4-13-88

Photographer M Doolan

Camera 35 mm

Film 100 ASA

Direction N

Subject Sections W and X, east side of site Stockpiles of soil to be  
wet sieved

\*\*\*\*\*



Exp Number 2

Date 4-13-88

Photographer M Doolan

Camera 35 mm

Film 100 ASA

Direction NW

Subject Section P Stockpiles of materials to be processed

ON SCENE PHOTOGRAPHS



Exp Number 3

Date 4-13-88

Photographer M Doolan

Camera 35 mm

Film 100 ASA

Direction SW

Subject Silt fence at head of drainage ditch in Section J

\*\*\*\*\*



Exp Number 4

Date 4-13-88

Photographer M Doolan

Camera 35 mm

Film 100 ASA

Direction W

Subject Destroyed silt fence (hay bails) at the head of the drainage ditch  
in Section J Note erosion and sediments in ditch

ON SCENE PHOTOGRAPHS



Exp Number 5  
Date 4-13-88  
Photographer M Doolan  
Camera 35 mm  
Film 100 ASA  
Direction W

Subject Silt fence at ditch in Section J with erosion into ditch


\*\*\*\*\*



Exp Number 6  
Date 4-13-88  
Photographer M Doolan  
Camera 35 mm  
Film 100 ASA  
Direction NE

Subject Section Q and north portion of site Dry shaker sieve operating  
in background


ON SCENE PHOTOGRAPHS



Exp Number 7  
Date 4-13-88  
Photographer M Doolan  
Camera 35 mm  
Film 100 ASA  
Direction E

Subject Section Q and P Stockpiles of material to be processed in background  
Head of ditch in Section J in foreground

\*\*\*\*\*



Exp Number 8  
Date 4-13-88  
Photographer M Doolan  
Camera 35 mm  
Film 100 ASA  
Direction N/A

Subject Stockpile in Section P


ON SCENE PHOTOGRAPHS



Exp Number 9  
Date 4-13-88  
Photographer M Doolan  
Camera 35 mm  
Film 100 ASA  
Direction N/A

Subject Closeup of stockpile in Section J


\*\*\*\*\*



Exp Number 10  
Date 4-13-88  
Photographer M Doolan  
Camera 35 mm  
Film 100 ASA  
Direction N/A

Subject Stockpiles in Section P

ON SCENE PHOTOGRAPHS



Exp Number 11  
Date 4-13-88  
Photographer M Doolan  
Camera 35 mm  
Film 100 ASA  
Direction N/A

Subject Closeup of stockpile in Section P

\*\*\*\*\*



Exp Number 12  
Date 4-13-88  
Photographer M Doolan  
Camera 35 mm  
Film 100 ASA  
Direction SE

Subject Wet sieve and stockpiles in Section X

ON SCENE PHOTOGRAPHS



Exp Number 13  
Date 4-13-88  
Photographer M Doolan  
Camera 35 mm  
Film 100 ASA  
Direction N

Subject Dry shaker sieve operation in Section Z

\*\*\*\*\*



Exp Number 14  
Date 4-13-88  
Photographer M Doolan  
Camera 35 mm  
Film 100 ASA  
Direction N

Subject Dry shaker sieve operation in Section Z




ON SCENE PHOTOGRAPHS



Exp Number 15  
Date 4-13-88  
Photographer M Doolan  
Camera 35 mm  
Film 100 ASA  
Direction W

Subject Dry Shaker sieve operation in Section Z Clay pigeon fragment falling  
into truck and fines falling to the ground


\*\*\*\*\*



Exp Number 16  
Date 4-13-88  
Photographer M Doolan  
Camera 35 mm  
Film 100 ASA  
Direction W

Subject Landscaping completed around ECA building

ON SCENE PHOTOGRAPHS



Exp Number 17  
Date 4-13-88  
Photographer M Doolan  
Camera 35 mm  
Film 100 ASA  
Direction N

Subject Landscaping completed around ECA building

\*\*\*\*\*



Exp Number 18  
Date 4-13-88  
Photographer M Doolan  
Camera 35 mm  
Film 100 ASA  
Direction N

Subject Kingston Construction operator cleaning and re-constructing drainage ditch adjacent to ECA property Silt fence intact and stable


ON SCENE PHOTOGRAPHS



Exp Number 19  
Date 4-13-88  
Photographer M Doolan  
Camera 35 mm  
Film 100 ASA  
Direction SW

Subject Section Q seen from Section R

\*\*\*\*\*



Exp Number 20  
Date 4-13-88  
Photographer M Doolan  
Camera 35 mm  
Film 100 ASA  
Direction S

Subject Central portion of site, Sections P,Q, X, and W seen from Section R  
Wet sieve in center of photo

ON SCENE PHOTOGRAPHS



Exp Number 21  
Date 4-13-88  
Photographer M Doolan  
Camera 35 mm  
Film 100 ASA  
Direction S

Subject Completion of cleaning in Section AA

\*\*\*\*\*



Exp Number 22  
Date 4-13-88  
Photographer M Doolan  
Camera 35 mm  
Film 100 ASA  
Direction NE

Subject Section EE (treed area) remaining to be cleaned